

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/05/2012	3. Time Prepared 1730
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
1100	Helicopter briefing, take off. Observations: <ul style="list-style-type: none"> Observed Turbidity Control Structure empty. Turbidity Control Structure erosion caused by the structure failure on Saturday. Observed Flooded pond in rock quarry from the failure of Turbidity Control Structure on Saturday. Observed the Talmadge Creek bypass open near MP1.6. Observed restoration work along Talmadge Creek near MP1.9. Observed Frac-City Soil Cells A & B. Soils were being loaded for disposal off site. Observed Frac-City crews decontaminating hose and a frac-tank. Talmadge Creek near MP1.9- observed crews installing dewatering pumps. Observed Talmadge Creek restoration work near A Drive. Observed crews preparing to unhook the bypass at the Creek portion of Confluence. Turbidity observed at the Confluence. Talmadge Creek- observed crews excavating to detach the bypass. Sheen observed and sheet piling prior to the confluence. OB8.97I- no work observed. OB9.10 LDB- no work observed. MP10.37 RDB- no work observed. MP21.5 Oxbow- flooding observed. Observed flooding at MP26.0. Observed flooding at MP27.0 Shady Bend Campground. 			
1230	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				